Mobile Paint Mfg. Co., Inc.

SAFETY DATA SHEET

OSHA HCS (29 CFR 1910-1200)

SECTION 1 - PRODUCT AND MANUFACTURER IDENTIFICATION

Product Name: NET DIP BLACK Product Code: 20-EX-6 Mobile Paint Mfg. Co., Inc. P.O. Box 717 4775 Hamilton Blvd. Theodore, AL 36582

Emergency Phone: Chemtel, Inc 1-800-255-3924 +1-813-248-0585 (Chemtel 24 Hour Emergency Number)

Information Phone: 251-443-6110 FAX: 251-408-0410

Product Use: Paint Not recommended for: Contact Manufacturer

SECTION 2 - HAZARD DATA

GHS Ratings:

Flammable liquid 3 Flash point >= 23°C and <= 60°C (140°F) Skin corrosive 2 Reversible adverse effects in dermal tissue, Draize score: >= 2.3 < 4.0 or persistent inflammation Carcinogen 2 Carcinogen 2 Limited evidence of human or animal carcinogenicity Aspiration hazard 1 Aspiration Toxicity Category 1: Known (regarded)- human evidence - hydrocarbons with kinematic viscosity ? 20.5 mm2/s at 40° C. GHS Hazards H226 Flammable liquid and vapour H304 May be fatal if swallowed and enters airways H315 Causes skin irritation H351 Suspected of causing cancer GHS Precautions P201 P201 Obtain special instructions before use P202 Do not handle until all safety precautions have been read and understood P233 Keep container tightly closed P240 Ground/bond container and receiving equipment P242 Use only non-sparking tools P243 Take precautionary measures agiants tatic discharge P244 Wash hands and skin thoroughly after handling P243 Take precautionary measures agiants tatic discharge P244 Wash hands and skin thoroughly after h	<u></u>	<u></u>		
2.3 < 4.0 or persistent inflammationCarcinogen2Aspiration hazard1Aspiration hazard1Aspiration Toxicity Category 1: Known (regarded)- human evidence - hydrocarbons with kinematic viscosity ? 20.5 mm2/s at 40° C.GHS HazardsH226Flammable liquid and vapourH304May be fatal if swallowed and enters airwaysH315Causes skin irritationH351Suspected of causing cancerGHS PrecautionsP201Obtain special instructions before useP202Do not handle until all safety precautions have been read and understoodP203Keep container tightly closedP240Ground/bond container and receiving equipmentP241Use explosion-proof electrical/ ventilating/ lighting/ equipmentP243Take precautionary measures against static dischargeP264Wash hands and skin thoroughly after handlingP280Wear protective gloves/protective clothing/eye protection/face protectionP281Use personal protective elipment (see information on this label)P331Do NOT induce vomitingP322Take off contaminated clothing and wash before reuseP331Do NOT induce vomitingP362Take off contaminated clothing and wash before reuseP303+P361+P353IF ON SKIN (or hair): Remove/Take off immediately all contaminated clothing.		Flammable liquid	3	Flash point >= 23°C and <= 60°C (140°F)
Carcinogen2Limited evidence of human or animal carcinogenicityAspiration hazard1Aspiration Toxicity Category 1: Known (regarded)- human evidence - hydrocarbons with kinematic viscosity ? 20.5 mm2/s at 40° C.GHS HazardsH226Flammable liquid and vapour H304H304May be fatal if swallowed and enters airways H315Causes skin irritation H351Causes skin irritation H351H220Do tan backet of causing cancerGHS PrecautionsP201Obtain special instructions before use P202P202Do not handle until all safety precautions have been read and understood Keep away from heat/sparks/open flames/hot surfaces – No smoking P233P240Ground/bond container and receiving equipment P241P241Use explosion-proof electrical ventilating/ lighting/ equipmentP243Take precautionary measures against static discharge P243P281Use personal protective equipment as required P231P281Use personal protective equipment as required P231P281Use personal protective clothing/eye protection/face protection P281P381Do NOT induce vomiting P382P382Take of contaminated clothing and wash before reuse P301+P310P301+P353IF ON SKIN (or hair): Remove/Take off immediately all contaminated clothing.		Skin corrosive	2	
Aspiration hazard1Aspiration Toxicity Category 1: Known (regarded)- human evidence - hydrocarbons with kinematic viscosity ? 20.5 mm2/s at 40° C.GHS HazardsH226Flammable liquid and vapour H304May be fatal if swallowed and enters airways H315Causes skin irritation H351H351Causes skin irritation H351Suspected of causing cancerGHS PrecautionsP201Obtain special instructions before use P202Do not handle until all safety precautions have been read and understood P210P233Keep away from heat/sparks/open flames/hot surfaces – No smoking P233Keep container tightly closed Ground/bond container and receiving equipment P241P242Use explosion-proof electrical/ ventilating/ lighting/ equipment P242Vase papersaning tools P264P264Wash hands and skin thoroughly after handling P280Wear protective gloves/protective clothing/eye protection/face protection P281P281Use personal protective equipment as required P331Do NOT induce vomiting P362P301+P310IF SWALLOWED: Immediately call a POISON CENTER or doctor/physician P301+P353P303+P361+P353IF ON SKIN (or hair): Remove/Take of immediately all contaminated clothing.		0	0	•
evidence - hydrocarbons with kinematic viscosity ? 20.5 mm2/s at 40° C. GHS Hazards H226 Flammable liquid and vapour H304 May be fatal if swallowed and enters airways H315 Causes skin irritation H351 Suspected of causing cancer GHS Precautions P201 P201 Obtain special instructions before use P202 Do not handle until all safety precautions have been read and understood P210 Keep away from heat/sparks/open flames/hot surfaces – No smoking P233 Keep container tightly closed P240 Ground/bond container and receiving equipment P241 Use explosion-proof electrical/ ventilating/ lighting/ equipment P242 Use only non-sparking tools P243 Take precautionary measures against static discharge P264 Wash hands and skin thoroughly after handling P280 Wear protective equipment as required P321 Specific treatment (see information on this label) P281 Use personal protective equipment as required P321 Specific treatment (see information on this label) P331 Do NOT induce vomiting P362 <td< td=""><td></td><td>-</td><td></td><td>• •</td></td<>		-		• •
H226Flammable liquid and vapourH304May be fatal if swallowed and enters airwaysH315Causes skin irritationH351Suspected of causing cancerGHS PrecutionsP201Obtain special instructions before useP202Do not handle until all safety precautions have been read and understoodP210Keep away from heat/sparks/open flames/hot surfaces – No smokingP233Keep container tightly closedP240Ground/bond container and receiving equipmentP241Use explosion-proof electrical/ ventilating/ lighting/ equipmentP242Use only non-sparking toolsP243Take precautionary measures against static dischargeP264Wash hands and skin thoroughly after handlingP280Wear protective gloves/protective clothing/eye protection/face protectionP281Use personal protective equipment as requiredP321Specific treatment (see information on this label)P331Do NOT induce vomitingP362Take off contaminated clothing and wash before reuseP301+P310IF SWALLOWED: Immediately call a POISON CENTER or doctor/physicianP302+P352IF ON SKIN: Wash with soap and waterP303+P361+P353IF ON SKIN (or hair): Remove/Take off immediately all contaminated clothing.		Aspiration nazard	1	evidence - hydrocarbons with kinematic viscosity ? 20.5
H304May be fatal if swallowed and enters airwaysH315Causes skin irritationH315Suspected of causing cancerGHS PrecautionsP201Obtain special instructions before useP202Do not handle until all safety precautions have been read and understoodP210Keep away from heat/sparks/open flames/hot surfaces – No smokingP233Keep container tightly closedP240Ground/bond container and receiving equipmentP241Use explosion-proof electrical/ ventilating/ lighting/ equipmentP242Use only non-sparking toolsP243Take precautionary measures against static dischargeP264Wash hands and skin thoroughly after handlingP280Wear protective gloves/protective clothing/eye protection/face protectionP281Use personal protective equipment as requiredP321Specific treatment (see information on this label)P331Do NOT induce vomitingP362Take off contaminated clothing and wash before reuseP301+P310IF SWALLOWED: Immediately call a POISON CENTER or doctor/physicianP302+P352IF ON SKIN (or hair): Remove/Take off immediately all contaminated clothing.	<u>GHS Ha</u>	<u>izards</u>		
H315 H351Causes skin irritationH351Suspected of causing cancerGHS PrecautionsGHS PrecautionsP201Obtain special instructions before useP202Do not handle until all safety precautions have been read and understoodP210Keep away from heat/sparks/open flames/hot surfaces – No smokingP233Keep container tightly closedP240Ground/bond container and receiving equipmentP241Use explosion-proof electrical/ ventilating/ lighting/ equipmentP242Use only non-sparking toolsP243Take precautionary measures against static dischargeP264Wash hands and skin thoroughly after handlingP280Wear protective gloves/protective clothing/eye protection/face protectionP281Use personal protective equipment as requiredP321Specific treatment (see information on this label)P331Do NOT induce vomitingP362Take off contaminated clothing and wash before reuseP301+P310IF SWALLOWED: Immediately call a POISON CENTER or doctor/physicianP302+P352IF ON SKIN (or hair): Remove/Take off immediately all contaminated clothing.		H226	Flammable liquid an	d vapour
H351Suspected of causing cancerGHS PrecautionsP201Obtain special instructions before useP202Do not handle until all safety precautions have been read and understoodP210Keep away from heat/sparks/open flames/hot surfaces – No smokingP233Keep container tightly closedP240Ground/bond container and receiving equipmentP241Use explosion-proof electrical/ ventilating/ lighting/ equipmentP242Use only non-sparking toolsP243Take precautionary measures against static dischargeP264Wash hands and skin thoroughly after handlingP280Wear protective gloves/protective clothing/eye protection/face protectionP281Use personal protective equipment as requiredP321Specific treatment (see information on this label)P362Take off contaminated clothing and wash before reuseP301+P310IF SWALLOWED: Immediately call a POISON CENTER or doctor/physicianP302+P352IF ON SKIN: Wash with soap and waterP303+P361+P353IF ON SKIN (or hair): Remove/Take off immediately all contaminated clothing.		H304	May be fatal if swalld	owed and enters airways
GHS PrecautionsP201Obtain special instructions before useP202Do not handle until all safety precautions have been read and understoodP210Keep away from heat/sparks/open flames/hot surfaces – No smokingP233Keep container tightly closedP240Ground/bond container and receiving equipmentP241Use explosion-proof electrical/ ventilating/ lighting/ equipmentP242Use only non-sparking toolsP243Take precautionary measures against static dischargeP264Wash hands and skin thoroughly after handlingP280Wear protective gloves/protective clothing/eye protection/face protectionP281Use personal protective equipment as requiredP321Specific treatment (see information on this label)P331Do NOT induce vomitingP362Take off contaminated clothing and wash before reuseP301+P310IF SWALLOWED: Immediately call a POISON CENTER or doctor/physicianP303+P361+P353IF ON SKIN (or hair): Remove/Take off immediately all contaminated clothing.		H315	Causes skin irritatior	1
P201Obtain special instructions before useP202Do not handle until all safety precautions have been read and understoodP210Keep away from heat/sparks/open flames/hot surfaces – No smokingP233Keep container tightly closedP240Ground/bond container and receiving equipmentP241Use explosion-proof electrical/ ventilating/ lighting/ equipmentP242Use only non-sparking toolsP243Take precautionary measures against static dischargeP264Wash hands and skin thoroughly after handlingP280Wear protective gloves/protective clothing/eye protection/face protectionP281Use personal protective equipment as requiredP321Specific treatment (see information on this label)P331Do NOT induce vomitingP362Take off contaminated clothing and wash before reuseP301+P310IF SWALLOWED: Immediately call a POISON CENTER or doctor/physicianP302+P352IF ON SKIN: Wash with soap and waterP303+P361+P353IF ON SKIN (or hair): Remove/Take off immediately all contaminated clothing.		H351	Suspected of causin	g cancer
P202Do not handle until all safety precautions have been read and understoodP210Keep away from heat/sparks/open flames/hot surfaces – No smokingP233Keep container tightly closedP240Ground/bond container and receiving equipmentP241Use explosion-proof electrical/ ventilating/ lighting/ equipmentP242Use only non-sparking toolsP243Take precautionary measures against static dischargeP264Wash hands and skin thoroughly after handlingP280Wear protective gloves/protective clothing/eye protection/face protectionP281Use personal protective equipment as requiredP321Specific treatment (see information on this label)P331Do NOT induce vomitingP362Take off contaminated clothing and wash before reuseP301+P310IF SWALLOWED: Immediately call a POISON CENTER or doctor/physicianP303+P361+P353IF ON SKIN (or hair): Remove/Take off immediately all contaminated clothing.	<u>GHS Pro</u>	ecautions		
P210Keep away from heat/sparks/open flames/hot surfaces – No smokingP233Keep container tightly closedP240Ground/bond container and receiving equipmentP241Use explosion-proof electrical/ ventilating/ lighting/ equipmentP242Use only non-sparking toolsP243Take precautionary measures against static dischargeP264Wash hands and skin thoroughly after handlingP280Wear protective gloves/protective clothing/eye protection/face protectionP281Use personal protective equipment as requiredP321Specific treatment (see information on this label)P362Take off contaminated clothing and wash before reuseP301+P310IF SWALLOWED: Immediately call a POISON CENTER or doctor/physicianP303+P361+P353IF ON SKIN (or hair): Remove/Take off immediately all contaminated clothing.		P201	Obtain special instru	ctions before use
P233Keep container tightly closedP240Ground/bond container and receiving equipmentP241Use explosion-proof electrical/ ventilating/ lighting/ equipmentP242Use only non-sparking toolsP243Take precautionary measures against static dischargeP264Wash hands and skin thoroughly after handlingP280Wear protective gloves/protective clothing/eye protection/face protectionP281Use personal protective equipment as requiredP321Specific treatment (see information on this label)P331Do NOT induce vomitingP362Take off contaminated clothing and wash before reuseP301+P310IF SWALLOWED: Immediately call a POISON CENTER or doctor/physicianP302+P352IF ON SKIN: Wash with soap and waterP303+P361+P353IF ON SKIN (or hair): Remove/Take off immediately all contaminated clothing.		P202	Do not handle until a	all safety precautions have been read and understood
P240Ground/bond container and receiving equipmentP241Use explosion-proof electrical/ ventilating/ lighting/ equipmentP242Use only non-sparking toolsP243Take precautionary measures against static dischargeP264Wash hands and skin thoroughly after handlingP280Wear protective gloves/protective clothing/eye protection/face protectionP281Use personal protective equipment as requiredP321Specific treatment (see information on this label)P331Do NOT induce vomitingP362Take off contaminated clothing and wash before reuseP301+P310IF SWALLOWED: Immediately call a POISON CENTER or doctor/physicianP302+P352IF ON SKIN: Wash with soap and waterP303+P361+P353IF ON SKIN (or hair): Remove/Take off immediately all contaminated clothing.		P210	Keep away from heat/sparks/open flames/hot surfaces – No smoking	
P241Use explosion-proof electrical/ ventilating/ lighting/ equipmentP242Use only non-sparking toolsP243Take precautionary measures against static dischargeP264Wash hands and skin thoroughly after handlingP280Wear protective gloves/protective clothing/eye protection/face protectionP281Use personal protective equipment as requiredP321Specific treatment (see information on this label)P331Do NOT induce vomitingP362Take off contaminated clothing and wash before reuseP301+P310IF SWALLOWED: Immediately call a POISON CENTER or doctor/physicianP302+P352IF ON SKIN: Wash with soap and waterP303+P361+P353IF ON SKIN (or hair): Remove/Take off immediately all contaminated clothing.		P233	Keep container tightly closed	
P242Use only non-sparking toolsP243Take precautionary measures against static dischargeP264Wash hands and skin thoroughly after handlingP280Wear protective gloves/protective clothing/eye protection/face protectionP281Use personal protective equipment as requiredP321Specific treatment (see information on this label)P331Do NOT induce vomitingP362Take off contaminated clothing and wash before reuseP301+P310IF SWALLOWED: Immediately call a POISON CENTER or doctor/physicianP302+P352IF ON SKIN: Wash with soap and waterP303+P361+P353IF ON SKIN (or hair): Remove/Take off immediately all contaminated clothing.		P240	Ground/bond contair	ner and receiving equipment
P243Take precautionary measures against static dischargeP264Wash hands and skin thoroughly after handlingP280Wear protective gloves/protective clothing/eye protection/face protectionP281Use personal protective equipment as requiredP321Specific treatment (see information on this label)P331Do NOT induce vomitingP362Take off contaminated clothing and wash before reuseP301+P310IF SWALLOWED: Immediately call a POISON CENTER or doctor/physicianP302+P352IF ON SKIN: Wash with soap and waterP303+P361+P353IF ON SKIN (or hair): Remove/Take off immediately all contaminated clothing.		P241	Use explosion-proof	electrical/ventilating/lighting/equipment
P264Wash hands and skin thoroughly after handlingP280Wear protective gloves/protective clothing/eye protection/face protectionP281Use personal protective equipment as requiredP321Specific treatment (see information on this label)P331Do NOT induce vomitingP362Take off contaminated clothing and wash before reuseP301+P310IF SWALLOWED: Immediately call a POISON CENTER or doctor/physicianP302+P352IF ON SKIN: Wash with soap and waterP303+P361+P353IF ON SKIN (or hair): Remove/Take off immediately all contaminated clothing.		P242	Use only non-sparki	ng tools
P280Wear protective gloves/protective clothing/eye protection/face protectionP281Use personal protective equipment as requiredP321Specific treatment (see information on this label)P331Do NOT induce vomitingP362Take off contaminated clothing and wash before reuseP301+P310IF SWALLOWED: Immediately call a POISON CENTER or doctor/physicianP302+P352IF ON SKIN: Wash with soap and waterP303+P361+P353IF ON SKIN (or hair): Remove/Take off immediately all contaminated clothing.		P243	Take precautionary r	neasures against static discharge
P281Use personal protective equipment as requiredP321Specific treatment (see information on this label)P331Do NOT induce vomitingP362Take off contaminated clothing and wash before reuseP301+P310IF SWALLOWED: Immediately call a POISON CENTER or doctor/physicianP302+P352IF ON SKIN: Wash with soap and waterP303+P361+P353IF ON SKIN (or hair): Remove/Take off immediately all contaminated clothing.		P264	Wash hands and ski	n thoroughly after handling
P321Specific treatment (see information on this label)P331Do NOT induce vomitingP362Take off contaminated clothing and wash before reuseP301+P310IF SWALLOWED: Immediately call a POISON CENTER or doctor/physicianP302+P352IF ON SKIN: Wash with soap and waterP303+P361+P353IF ON SKIN (or hair): Remove/Take off immediately all contaminated clothing.		P280	Wear protective glov	es/protective clothing/eye protection/face protection
P331Do NOT induce vomitingP362Take off contaminated clothing and wash before reuseP301+P310IF SWALLOWED: Immediately call a POISON CENTER or doctor/physicianP302+P352IF ON SKIN: Wash with soap and waterP303+P361+P353IF ON SKIN (or hair): Remove/Take off immediately all contaminated clothing.		P281	Use personal protect	tive equipment as required
P362Take off contaminated clothing and wash before reuseP301+P310IF SWALLOWED: Immediately call a POISON CENTER or doctor/physicianP302+P352IF ON SKIN: Wash with soap and waterP303+P361+P353IF ON SKIN (or hair): Remove/Take off immediately all contaminated clothing.		P321	Specific treatment (s	see information on this label)
P301+P310IF SWALLOWED: Immediately call a POISON CENTER or doctor/physicianP302+P352IF ON SKIN: Wash with soap and waterP303+P361+P353IF ON SKIN (or hair): Remove/Take off immediately all contaminated clothing.		P331	Do NOT induce vom	iting
P302+P352IF ON SKIN: Wash with soap and waterP303+P361+P353IF ON SKIN (or hair): Remove/Take off immediately all contaminated clothing.		P362	Take off contaminate	ed clothing and wash before reuse
P303+P361+P353 IF ON SKIN (or hair): Remove/Take off immediately all contaminated clothing.		P301+P310	IF SWALLOWED: In	nmediately call a POISON CENTER or doctor/physician
		P302+P352	IF ON SKIN: Wash v	vith soap and water
		P303+P361+P353	· · ·	

P308+P313	IF exposed or concerned: Get medical advice/attention
P332+P313	If skin irritation occurs: Get medical advice/attention
P370+P378	In case of fire: Use dry sand, dry chemical or alcohol-resistant foam for extinction
P405	Store locked up
P403+P235	Store in a well ventilated place. Keep cool
P501	Dispose of contents/container in accordance with all local, regional, national and international regulations.

Signal Word: Danger



SECTION 3 - COMPOSITION / HAZARDOUS INGREDIENTS Chemical Name CAS number Weight Concentration %

ethyl benzene	100-41-4	0.28%
mineral spirits	8052-41-3	50.00% - 60.00%

SECTION 4 - FIRST AID MEASURES

Inhalation: Remove to fresh air. Administer oxygen if breathing is difficult. Restore breathing if necessary and call a physian immediately. Treat symptomatically.

Eyes: Remove contact lenses if worn. Flush immediately with large amounts of water for at least 15 minutes. If symptoms persist, consult with a doctor for medical treatment.

Skin: Wash affected areas with soap and water. Remove and launder contaminated clothing. Consult a doctor if skin irritation continues.

Ingestion: Do not induce vomiting. Rinse out mouth and drink plenty of water to dilute. Never give anything by mouth to an unconcious person. Get medical help immediately.

Most important symptoms and effects, both acute and delayed

Symptoms: No information available.

Indication of any immediate medical attention and special treatment needed

Note to physicians: Treat symptomatically

SECTION 5 - FIRE FIGHTING MEASURES

Flash Point:	41 C (106 F)
LEL: 1.00	

UEL: 6.00

Extinguishing media

Suitable extinguishing agents:

Use extinguishing measures that are appropriate to local circumstances and the surrounding environment. CO2, extinguishing powder or water spray may be effective.

For safety reasons unsuitable extinguishing agents: CAUTION! Use of water spray may be inefficient.

Unusual Fire and Explosion Hazards

Closed containers may explode when exposed to extreme heat. Application to hot surfaces requires special precautions. Full protective equipment including self-contained breathing apparatus should be used. Water spray may be ineffective. If water is used, fog nozzles are preferable. Water may be used to cool closed containers.

Special hazards arising from the substance or mixture

Formation of toxic gases is possible during heating or in case of fire.

Advice for firefighters

During emergency conditions overexposure to decomposition products may cause a health hazard. Symptoms may not be immediately apparent. Obtain medical attention. Keep containers tightly closed. Isolate from heat, sparks, and open flame.

Protective equipment:

Full protective quipment including self-contained breathing apparatus should be used.

SECTION 6 - ACCIDENTAL RELEASE MEASURES

Personal precautions, protective equipment and emergency procedures

Use respiratory protective device against the effects of fumes/dust/aerosol. Wear protective equipment. Keep unprotected persons away. Ensure adequate ventilation. Keep away from ignition sources. Protect from heat. **Environmental precautions:** Do not allow to enter sewers/ surface or ground water. See Section 12 for additional ecological information.

Methods and material for containment and cleaning up:

Absorb with non-combustible liquid-binding material (sand, diatomite, acid binders, universal binders). Dispose contaminated material as waste according to item 13. Do not flush with water or aqueous cleansing agents. Send for recovery or disposal in suitable receptacles.

Reference to other sections

See Section 7 for information on safe handling.

See Section 8 for information on personal protection equipment.

See Section 13 for disposal information.

SECTION 7 - HANDLING AND STORAGE

Handling Precautions:

Precautions for safe handling

Prevent formation of fine mist and vapor buildup during and after use. Avoid splashes or spray in enclosed areas. Use only in well ventilated areas. Do not get in eyes. Avoid skin contact. Can cause allergic respiratory reaction. Can cause allergic skin reaction. Prevent prolonged or repeated breathing of vapors or spray mist. Avoid breathing of sanding dust. Wash contaminated clothing thoroughly. Wash skin thoroughly with soap and water after handling. Close container after each use. Do not transfer this product to unlabeled containers. Do not handle until the manufacturer's safety precautions have been read and understood. Keep out of reach of children.

Information about protection against explosions and fires:

Keep ignition sources away. Do not smoke. Protect against electrostatic discharges.

Storage Requirements:

Do not store above 120 F. Store large quantities only in buildings designed to comply with OSHA 1910.106. Keep closures tight and container upright to prevent leakage. Do not store or use near heat, sparks or flame. Never use pressure to empty. Drum must not be washed out or used for other purposes. Drums of this material should be grounded when pouring.

Regulatory Requirements:

Consult NFPA Code. Use approved bonding and grounding procedures.

SECTION 8 - EXPOSURE CONTROLS / PERSONAL PROTECTION						
Chemical Name / CAS No.	OSHA Exposure Limits	ACGIH Exposure Limits	Other Exposure Limits			
ethyl benzene 100-41-4	TLV-TWA 100ppm PEL-TWA 100ppm STEL 125 ppm	TWA 20ppm	NIOSH REL TWA 100ppm NIOSH REL ST 125ppm			
mineral spirits 8052-41-3	OSHA Z-1 500 ppm - TWA OSHA Z-1 1000 mg/m3 - TWA	ACGIH TLV 200 mg/m3 - TWA	Not Established			

Engineering Controls:

Appropriate engineering controls include ventilations systems, eyewash stations and emergency showers.

Ventilation:

All application areas should be ventilated in accordance to OSHA regulation 29 CFR 1910.94, 1910.107, 1910.108. Remove decomposition products formed during welding or flame cutting on surface coated with this product. If baking, vent fumes.

Work / Hygenic Practices:

Wash skin thoroughly before breaks and meals and at the end of work period .

Respiratory Protection:

Use a NIOSH-approved respirator to prevent overexposure, when exposure exceeds occupational exposure limits (Section 8). Use either an atmosphere-supplying respirator or an air-purifying respirator for organic vapors in compliance with 29 CFR 1910.134, with provision for mist removal if conditions so indicate. If isocyanate compounds are present in spray applications or other situations which may produce inhalation exposures, use a respirator that is recommended or approved for use in isocyanate-containing environments.

Eye Protection:

Safety eyewear including splashguards or side shields recommended.

Protective Gloves:

Recommended. The glove material has to be impermeable and resistant to the product/ the substance/ the preparation. Selection of the glove material should be based on consideration of the penetration times, rates of diffusion and the degradation.

Other Protective Clothing or Equipment:

Use protective outerwear and prevent prolonged skin contact with contaminated clothing.

Contaminated Equipment:

Thoroughly clean all contaminated clothing and personal protection equipment.

SECTION 9 - PHYSICAL / CHEMICAL CHARACTERISTICS

Information on basic physical and chemical properties

Appearance: Liquid	Odor: Typical solvent paint odor
Vapor Pressure: 1.2 mmHg	Odor threshold: No information available
Vapor Density: 5.0	pH: No information available
Specific Gravity: 0.89	Melting point: No information available
Freezing point: No information available	Solubility: No information available
Boiling range: 149°C	Flash point: 106 F,41 C
Evaporation rate: slower than ether	Flammability: No information available
Partition coefficient (n- no data octanol/water):	Decomposition temperature: No information available
Viscosity: No information available	VOC - water/exempt (g/L) 497
VOC - water/exempt (lb/gal) 4.14	VOC emitted (g/L) 497
VOC emitted (lb/gal) 4.14	

SECTION 10 - STABILITY AND REACTIVITY

Reactivity - No data available

Chemical stability - Stable under recommended storage conditions.

STABLE

Possibility of Hazardous Reactions - None under normal conditions of use. Conditions to Avoid - Heat, sparks, open flame, static electricity, sources of ignition, elevated temperatures.

Incompatible Materials - Strong acids and alkali, strong oxidizing agents.

Incompatibility of Individual Components:

No information available

Hazardous decomposition products - Carbon monoxide and carbon dioxide Information for Individual Components:

SECTION 11 - TOXICOLOGICAL INFORMATION

Mixture Toxicity

Dermal Toxicity LD50: 3,867mg/kg

Component Toxicity

 ponone rokiony	
100-41-4	ethyl benzene
	Oral LD50: 3,500 mg/kg (rat) Inhalation LC50: 4,000 ppm (rat)
8052-41-3	mineral spirits
	Oral LD50: 5,000 mg/kg (rat) Dermal LD50: 2,000 mg/kg (rabbit)

CHRONIC HEALTH HAZARDS:

Reports have associated repeated and prolonged overexposure to solvents with permanent brain and nervous system damage.

Routes of Entry:

Routes of Entry	•				
Inhalation	Skin C	ontact	Eye Contact	Ingestion	
Target Organs:					
Eyes	Lungs	Central Ne	rvous System	Skin	
Effects of Overe	xposure				
Eye contact:			t can cause severe n some individuals.	e irritation, redness, tearing, blurred vision. May be a	
Skin contact: Skin contact can cause moderate iritation, defatting, dermatitis. May be a sensi some individuals.		rate iritation, defatting, dermatitis. May be a sensitizer in			
Inhalation: Anesthetic, excessive inhalation can cause irritation of the respiratory trac nervous system depression characterized by headache, dizziness, stagge confusion, unconsciousness, coma and even asphyxiation.		haracterized by headache, dizziness, staggering gait,			
Ingestion:		Ingestion can cause gastrointestinal irritation, nausea, vomiting and diarrhea. Aspiration into the lungs during ingestion or vomiting may cause mild to severe pulmonary injury and possibly even death.			
Sensitization:		No data available.			
Mutagenicity:		No data ava	ailable.		
Reproductive Toxicity:		No data ava	ailable.		
Teratogenicity	/:	No data ava	ailable.		
Specific Targe Organ Toxicity Single Exposi	y -	No data ava	ailable.		
Specific Targe Organ Toxicity Repeated Exp	y -	No data ava	ailable.		

Carcinogenicity:

For Mixture - No information available

For Components - The following chemicals comprise 0.1% or more of this mixture and are listed and/or classified as carcinogens or potential carcinogens by NTP, IARC, OSHA (mandatory listing), or ACGIH (optional listing). **Note:** Reference to **ethyl benzene** refers to IARC classification of ethyl benzene as possibly carcinogenic to humans (Group 2B) based on sufficient evidence in experimental animals but there is inadequate evidence that ethyl benzene causes cancer in humans.

CAS Number

Description

<u>% Weight</u>

Carcinogen Rating

ethyl benzene: IARC: Group 2B -Possibly carcinogenic to humans ACGIH: Confirmed animal carcinogen with unknown relevance to humans OSHA: Not identified as a carcinogen or possible carcinogen NTP: Not identified as a known or anticipated carcinogen

SECTION 12 - ECOLOGICAL INFORMATION

Persistence and degradability - No information available. Bioaccumulative potential - No information available. Mobility in soil - No information available. Ecotoxical effects - No information available. Other adverse effects - No information available.

Additional ecological information:

General notes:

Do not allow product to reach ground water, water course or sewage system. Danger to drinking water if even small quantities leak into the ground.

Results of PBT and vPvB assessment

PBT: Not applicable. **vPvB:** Not applicable.

Component Ecotoxicity

mineral spirits

96 hr LC50 Oncorhynchus mykiss: 25 mg/l; 48 hr EL50 Daphnia magna: 1.4 mg/l; 72 hr EL50 Pseudokirchneriella subcapitata: 1 mg/l

SECTION 13 - DISPOSAL CONSIDERATIONS

Waste disposal methods:

Waste from this product may be hazardous as defined under the Resource Conservation and Recovery Act (RCRA) 40 CFR 261. Residual materials should be treated as hazardous unless proven to be otherwise.

Notice to user:

The user of this material has the responsibility to dispose of unused material, residues and containers in compliance with all relevant local, state and federal laws and regulations regarding treatment, storage and disposal for hazardous and nonhazardous wastes.

Empty Container Warning:

Emptied containers may contain product residue. Follow label warnings even after container is emptied. Residual vapors may explode on ignition. Do not reuse container.

SECTION 14 - TRANSPORT INFORMATION

Shipping descriptions are provided for informational purposes and do not consider container sizes. The presence of a shipping description for a particular mode of transportation does not indicate that the product is packaged suitably for that mode of transport. All packaging must be reviewed for suitability prior to shipment and compliance with applicable regulations is the sole responsibility of the person offering the product for transport.

<u>Agency</u>	<u>Proper Shipping Name</u>	<u>UN Number</u>	<u>Packing Group</u>	Hazard Class	
COT	Paint	1263	III	3	

California Proposition 65

This product contains the following chemicals which are listed by the State of California as carcinogenic or a reproductive toxin:

CERCLA

This material, as supplied, contains the following chemicals regulated as a hazardous substance under the Comprehensive Environmental Response Compensation and Liability Act (CERCLA) - 40 CFR 302

100-41-4 ethyl benzene

Hazardous Air Pollutants (HAPs) Content

Hazardous Air Pollutants subject to the provisions of the Clean Air Act, Title I Section 112 'National Emission Standards for Hazardous Air Pollutants'

100-41-4 ethyl benzene 0.3 %

Massachusetts RTK:

ethyl benzene 100-41-4

New Jersey RTK:

ethyl benzene 100-41-4 mineral spirits 8052-41-3

Pennsylvania RTK:

ethyl benzene 100-41-4 mineral spirits 8052-41-3

Rhode Island Hazardous Substance List:

ethyl benzene 100-41-4

SARA 313

This product contains a chemical or chemicals which are subject to the reporting requirements of Section 313 of Title III of the Superfund Amendments and Reauthorization Act of 1986 (SARA 313).

100-41-4 ethyl benzene 0.3 %

TSCA

All chemicals in this product are listed, or are exempt from listing, on the TSCA inventory unless they are listed here:

SECTION 16 - OTHER INFORMATION

Hazardous Material Information System (HMIS)



HMIS & NFPA Hazard Rating Legend * = Chronic Health Hazard 0 = INSIGNIFICANT 1 = SLIGHT 2 = MODERATE 3 = HIGH

DISCLAIMER: The information provided in this MSDS has been obtained from sources believed to be accurate and reliable. It is furnished without warranty of any kind, express or implied. Recipients should determine that the information is current and suitable for the protection of the environment and the health and safety of your employees and users of this product.

Date revised: 2015-09-17 Date Prepared: 9/17/2015 **Reviewer Revision 1**